



Sectional Chart: Washington
Runway: Rwy 01-19 H4003 x 75 (ASPH); Rwy 06-24 2650 x 200 (TURF)
 Rwy 06 thld dsplcd 200', Rwy 24 thld dsplcd 550'
Traffic Pattern: Left, TPA 1220 (800)
Runway Lights: MIRL
Rotating Beacon: Yes
Fuel: 100 LL
Maintenance: None
Manager: Ronnie Vaughan; 1145 Tuck Airport Road, South Boston, Virginia 24592; (434) 572-6991
Airport Telephone: (434) 476-3300
Airport Operators: County of Halifax; P. O. Box 699, Halifax, Virginia 24558; (434) 476-3300
 Hours of Operation: Attended 1300-2230Z±
Remarks: Terminal open – unattended. Self-fueling with credit card. Deer on and invof rwys. Rwy 05 outlined with yellow cones. Rwy 01 REIL OTS indef. ACTIVATE MIRL Rwy 01-19,

REIL Rwy 01 and Rwy 19 – CTAF. PAPI Rwy 01 and Rwy 19 opr continuously.
Points of Interest: Staunton River State Park, Buggs Island Lake, Occoneechee State Park, South Boston "Big Daddy" Speedway, Virginia International Raceway
Web Site: None
Weather Data Sources: None
Communications: CTAF/UNICOM 122.8, South Boston RCO 122.1R 110.4T (Leesburg Radio), Washington Center APP/DEP CON 124.05
Navigation Aids: South Boston (L) VORTAC 110.4
Published Instrument Approach: Yes
Approach Lighting: Rwy 01-19 REIL, PAPI

SOUTH BOSTON

Latitude N36°42.56'
 Longitude W78°50.90'

Field Elevation
 420